


Increase pressure on the left



Increase pressure on the right

If your pressure toggle does not appear to give you enough range of adjustment to produce acceptable results assure the printhead is installed correctly and that the ribbon strip plate is not impacting the media surface.